



Release Notes

General Description

This version update contains recent feature enhancements and fixes. It comprises the following.

Control Methods

Control version: 25.0.9.2
CDUe version: 004.000

i-SPEED 7 Camera Software and Firmware

Camera software version: 003.012
Camera firmware versions: 001.009 (CSY), 001.008 (CSE), 001.019 (I1M), 001.010 (I1G),
001.015 (I2M), 001.012 (I2F), 001.003 (LNW, LNW, LSW, LSE),
001.001 (PSU)

i-SPEED 5 Camera Software and Firmware

Camera software version: 003.012
Camera firmware versions: 000.012 (CSY), 000.011 (CSE), 000.013 (I1M), 000.009 (I1F),
000.003 (LN, LS), 000.002 (PSU)

Detailed Changes from the Previous Global Release

1. Language selection is now available to users running ControlONE.
2. Save to computer operations are now up to 3x faster.
3. Improved the reliability of save operations.
4. Added ControlONE/Control Multi-DAQ error report generation.
5. Non-Western characters in the camera ID no longer cause CDUe connection problems.

Installation Instructions

Refer to the "Update Guide" document included with the update package.

How to get Technical Support

Please email techsupport@ix-cameras.com . Please quote your camera serial number in all correspondences.